

Category 17: Initials

Page 52

CREATION | PRODUCTION | PERFECTION

1


2

3

4

5

A



1922 A 0.70_{gm}



1922 B 0.70_{gm}



1922 C 0.60_{gm}



1922 D 0.70_{gm}



1922 E 0.60_{gm}

B



1924 F 0.60_{gm}




1924 G 0.60_{gm}



1924 H 0.60_{gm}




1924 I 0.50_{gm}



1924 J 0.60_{gm}

C



1923 K 0.60_{gm}



1923 L 0.60_{gm}



1923 M 0.60_{gm}



1923 N 0.70_{gm}



1926 O 0.60_{gm}

D



1925 P 0.60_{gm}



1925 Q 0.60_{gm}



1925 R 0.60_{gm}



1925 S 0.60_{gm}



1925 T 0.60_{gm}

E



1926 U 0.70_{gm}



1926 V 0.60_{gm}



1926 W 0.70_{gm}



1924 I 0.60_{gm}




1927 Y 0.60_{gm}


F



1927 Z 0.60_{gm}




G89 A 0.50_{gm}



G89 B 0.80_{gm}




G89 E 0.60_{gm}




G89 F 0.70_{gm}


G




G89 J 0.70_{gm}




G89 K 0.70_{gm}



G89 L 0.70_{gm}



G89 M 0.90_{gm}



G89 U 0.70_{gm}


H



G89 W 1.00_{gm}



1928 A 0.70_{gm}



1928 B 0.80_{gm}



1928 C 0.90_{gm}



1928 D 1.10_{gm}



1 2 3 4 5

A	1929 E 0.50 _{gm}	1932 F 0.70 _{gm}	1932 G 0.70 _{gm}	1929 H 0.90 _{gm}	1931 J 0.60 _{gm}
B	1929 K 0.90 _{gm}	1930 L 0.70 _{gm}	1930 M 0.70 _{gm}	1930 N 0.60 _{gm}	1931 O 0.80 _{gm}
C	1933 P 0.60 _{gm}	1931 Q 0.80 _{gm}	1932 R 0.80 _{gm}	1932 S 0.70 _{gm}	1933 T 0.70 _{gm}
D	1931 U 0.70 _{gm}	1933 V 0.60 _{gm}	Ø6951 0.90 _{gm}	Ø6954 1.00 _{gm}	Ø6962 1.10 _{gm}
E	Ø6969 0.80 _{gm}	P003 0.50 _{gm}	M111 3.20 _{gm}	Ø7581 2.80 _{gm}	SS1888A 1.20 _{gm}
F	SS1886B 1.20 _{gm}	SS1889A 1.10 _{gm}	SS1884A 1.40 _{gm}	SS1880A 0.80 _{gm}	SS1883A 0.90 _{gm}
G	SS1884B 1.90 _{gm}	SS1888B 1.40 _{gm}	SS1886A 1.00 _{gm}	SS1885B 0.90 _{gm}	SS1881B 0.90 _{gm}
H	SS1890B 1.00 _{gm}	SS1880B 1.10 _{gm}	SS1820A 0.80 _{gm}	SS1883B 1.00 _{gm}	SS1887B 1.10 _{gm}



Category 17: Initials

Page 54

CREATION | PRODUCTION | PERFECTION

1 2 3 4 5

A					
	SS1890A 0.90 _{gm}	SS1882A 1.30 _{gm}	SS1882B 1.30 _{gm}	SS1881A 1.00 _{gm}	SS1887A 1.20 _{gm}
B					
	SS1889B 0.70 _{gm}	SS1823A 1.10 _{gm}	SS1885A 0.90 _{gm}	SS1820B 1.00 _{gm}	SS1823B 1.00 _{gm}
C					
	SS1855A 0.80 _{gm}	SS1855B 0.80 _{gm}	SS1818B 0.50 _{gm}	SS1818A 0.70 _{gm}	SS1875A 0.70 _{gm}
D					
	SS1875B 0.70 _{gm}	SS1874A 0.80 _{gm}	SS1874B 0.80 _{gm}	SS1873B 0.40 _{gm}	SS1873A 0.70 _{gm}
E					
	SS1722B 0.80 _{gm}	SS1722A 0.80 _{gm}	SS1841A 1.10 _{gm}	SS1841B 0.80 _{gm}	SS1872B 0.70 _{gm}
F					
	SS1872A 0.80 _{gm}	SS1839A 0.80 _{gm}	SS1839B 0.70 _{gm}	SS1837B 0.70 _{gm}	SS1837A 0.70 _{gm}
G					
	SS1877A 0.90 _{gm}	SS1877B 1.00 _{gm}	SS1879A 0.60 _{gm}	SS1879C 0.60 _{gm}	SS1879B 0.70 _{gm}
H					
	SS1817B 1.00 _{gm}	SS1863B 1.00 _{gm}	SS1859B 1.10 _{gm}	SS1876B 0.90 _{gm}	SS1860B 0.80 _{gm}



1

2

3

4

5

A



SS1817A 1.00 gm



SS1863C 0.80 gm



SS1863A 0.90 gm



SS1860C 0.90 gm



SS1876C 0.90 gm

B



SS1860A 1.00 gm



SS1862B 0.80 gm



SS1861B 1.00 gm



SS1859C 0.90 gm



SS1864C 0.90 gm

C



SS1862C 0.80 gm



SS1861C 0.90 gm



SS1876A 0.90 gm



SS1862A 1.00 gm



SS1864B 1.10 gm

D



SS1864A 0.80 gm



SS1859A 1.10 gm



SS1817C 0.90 gm

E

F

G

H

